| Form 3160-5 (November 1983) (Formerly 9-331) DEPARTMENT OF THE INTERIOR (Other instruction in the control of the interior of | N TRIPLICATE* Budget Bureau No. 1004-0138 Expires August 31, 1985 |
|---|--|
| BUREAU OF LAND MANAGEMENT | 5. LEASE DESIGNATION AND SERIAL NO |
| | SF 078065 |
| SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different Use "APPLICATION FOR PERMIT—" for such proposals.) | |
| OIL GAS OTHER | 7. UNIT AGREEMENT NAME |
| 2. NAME OF OPERATOR | 8. FARM OR LEASE NAME |
| Hixon Development Company 3. ADDRESS OF OPERATOR | South Bisti # |
| P.O. Box 2810, Farmington, N.M. 87499 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements See also space 17 below.) At surface | , and the state of |
| 1900' FNL, 990' FEL, Sec. 21, T25N, R12W | Bisti Lower Gallup 11. SEC., T., E., M., OR BLK. AND SURVEY OR ARMA |
| API #30-045-27 14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) | 784 Sec. 21, T25N, R12W 12. COUNTY OR PARISH 13. STATE |
| 6278' GLE | San Juan N.M. |
| 16. Check Appropriate Box To Indicate Nature of Notice | |
| NOTICE OF INTENTION TO: | SUBSEQUENT REPORT OF: |
| TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHU | |
| FRACTURE TREAT MULTIPLE COMPLETE FRACTURE T | |
| SHOOT OR ACIDIZE ABANDON* SHOOTING OF | |
| REPAIR WELL CHANGE PLANS (Other) | Drilling Progress X |
| (Other) (Note Comple 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give proposed work. If well is directionally deilled give subjurges locations and give | : Report results of multiple completion on Well etien or Recompletion Report and Log form.) |
| Spudded surface at 2:30 p.m. on June 7, 1 12-1/4" hole to 320' KB. Ran 7 jts. (304 24#, J-55, 8rd, ST&C casing. BakerLoked bottom of 1st jt. Ran centralizers on the 3rd, 5th and 6th jts. Casing set at 319. casing as follows: Mixed and pumped 200 ft.) Class "B" cement containing 2% CaCl2 cellophane flakes. Cement circulated to Presusre tested casing to 600 psi for 30 in | 990. Drilled 2.25') of 8-5/8", guide shoe on the tops of 1st, 67'. Cemented sks. (236 cu. 4 and 1/4#/sk. surface. |
| Tresuste tested casing to obo psi for 50 i | minutes; test Ok. |
| | JULI 6 1990 |
| | OIL CON. DIV. DIST. 3 |
| SIGNED Aldrich L. Kuchera mou | ACCEPTEME OF WELL & DIPO |

*See Instructions on Reverse Side

APPROVED BY ______CONDITIONS OF APPROVAL, IF ANY:

JUL 10 1990

FARMINGTON RESOURCE AREA