

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Giant Exploration & Production Company

3. Address and Telephone No.

P.O. Box 2810, Farmington, New Mexico 87499 (505) 326-3325

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

2400' FNL, 1820' FEL, Sec. 3, T25N, R11W

5. Lease Designation and Serial No.

NOO-C-14-20-3598

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Buena Suerte 3G Com #1

9. API Well No.

30-045-28646

10. Field and Pool, or Exploratory Area

Basin Fruitland Coal

11. County or Parish, State

San Juan, New Mexico

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment

TYPE OF ACTION

☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other Drilling Progress

☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded surface at 5:30 pm on January 23, 1992. Drilled 8-3/4" hole to 140'. Ran 3 jts. (130.77') of 7", 20#, J-55, 8rd, ST&C casing. Casing set at 132.77'. Mixed and pumped 65 sks. (76.7 cu. ft.) of Class "B" cement containing 2% CaCl₂ and 1/4#/sk. cellophane flakes. Cement circulated to surface. Pressure tested casing to 600 psi for 30 minutes; test ok.

ACCEPTED FOR RECORD

FEB 07 1992

FARMINGTON RESOURCE AREA

BY 2294

RECEIVED
BUREAU MAIL ROOM
92 FEB -6 AM 10:32
FARMINGTON RESOURCE AREA
FARMINGTON, NEW MEXICO

14. I hereby certify that the foregoing is true and correct

Signed Jeffrey R. Vaughan
(This space for Federal or State office use)

Title Engineering Manager

Date FEB 6 1992

Approved by _____
Conditions of approval, if any:

Title _____ Date _____