

Submit 3 Copies
to Appropriate
District Office

3 NMOC
1 File

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30 045 29216
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. IG-3734
7. Lease Name or Unit Agreement Name Bisti State
8. Well No. 90
9. Pool name or Wildcat Basin Fruitland Coal (71629)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	2. Name of Operator Dugan Production Corp.
3. Address of Operator PO Box 420, Farmington, NM 87499	4. Well Location Unit Letter <u>H</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>790</u> Feet From The <u>East</u> Line Section <u>2</u> Township <u>25N</u> Range <u>13W</u> NMPM <u>San Juan</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 6242' GL (est)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Spud, casing & cement ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Move in & rig up Wayne Smith. Spudded 9-1/8" hole at 11:30 AM 7-15-96. Drilled surface - 130'. TOH with bit. TIH with 4 jts. 7" 23# casing landed at 122'. Cement with 70 sx class "B" neat cement. Displace with 4 bbls water. Plug down at 1630 hrs. 7-15-96. Cement to surface.

Nipple up BOP. Pressure test to 600# - OK.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Gary Brink TITLE Operations Manager DATE 7/17/96
TYPE OR PRINT NAME Gary Brink TELEPHONE NO. 325-1821

(This space for State Use)

APPROVED BY Johnny Robinson DEPUTY OIL & GAS INSPECTOR, DIST. #3 DATE JUL 18 1996
CONDITIONS OF APPROVAL, IF ANY: