Form 9-331 a (Feb. 1951)

8 Х

(SUBMIT IN TRIPLICATE)

UNITED STATES

GEOLOGICAL SURVEY

DEPARTMENT OF THE INTERIOR

and Office	Santa	Fe,	N.M
ease No.	S F 0780	06 2	
_{Init} Ca	rson U	nit	

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO PULL OR ALTER CASING		SUBSEQUENT REPORT OF WATER SHUT-OFF
---	--	-------------------------------------

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

		A	ugust 11	, 19 60
Carson Unit Well No. 14-8 is locate	ed 659 ft. from	\mathbf{m}_{-} $\begin{cases} \mathbf{X} \mathbf{X} \mathbf{X} \\ \mathbf{S} \end{cases}$ line	and 658 ft. from ${W \choose W}$ line of	sec8
SW SW 8 (% Sec. and Sec. No.) Bisti (Field)	25 N (Twp.) San (Count	(Range) Juan y or Subdivision)	NMPM (Meridian) New Mexico (State or Territory)	

The elevation of the checicle decedereces devel is 6323... ft. (approx. ground)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Abandonment of location



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.				
Company Shell Oil Company				
Address P. O. Box 1200	Original signed by B. W. SHEPARD			
Farmington, New Mexico	B. W. Shepard Title Exploitation Engineer			
	1 ICIC			