NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

instructions in the Rules and Regulation	ns of the Commission. Indicate Nature of R	eport by Checking Be	elow	
REPORT ON BEGINNING REPORT ON R OF CASING SH			REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL	REPORT ON RECOPERATION	COMPLETION	REPORT ON (Other)Sandoil Fracture	x
	July	19, 1955	Farmington, New Men	rieo
	(Da		(Place)	
Following is a report on the work		J	704	
(Company or Op			(Lease)	••••
Cox Drilling (Contracto)	Company	, Well No45	in the SE 1/4 SW 1/4 of Sec.	36
T27N , R7W , NMPM , So		Cliff Pool	Rio Arriba	County
•	July 18, 19	-		, .
The Dates of this work were as folows:		C-101	6-20-55	
Notice of intention to do the work (was) (was not) submitted on For	m C-102 on	(Cross out incorrect words)	., 19,
and approval of the proposed plan (was) (was not) obtained. LED ACCOUNT OF WORL	Z DONE AND DEGN	TIME ORDAY THE	
July 18, 1955. Total De Sandoil Pictured Cliffs 15,000 pounds of sand, a Maximum treating pressur 29.0 barrels per minute. Witnessed by D. C. Johnston (Name)	formation from 2879 nd 500 pounds of Ad e 1300 psi. Flush Matural gage too	Matural Gas C (Company)	own pressure 3300 psi. of oil. Injection rate re. RECE JUL 21 OIL CON. DIST. O. Petroleum Engineer (Title)	3
Approved: OIL CONSERVATION (COMMISSION Murdy	to the best of my l	at the information given above is true and knowledge	complete
(Name)	(Position	aso Matural Gas Company	
Oil and Gas Inspector Dist	.#3. 7-72-	Representing BOX Address	997, Farmington, New Mexic	30