

(SUBMIT IN TRIPLICATE)

Indian Agency Sicarilla

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Alottee _____

Lease No. 237

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

12-28, 1962

Well No. 237 is located 220 ft. from N line and 200 ft. from E line of sec. 29

29 (1/4 Sec. and Sec. No.) 27 N (Twp.) 1E (Range) 100 W (Meridian)
Upton (Field) Upton (County or Subdivision) NEW MEXICO (State or Territory)

The elevation of the derrick floor above sea level is 1000 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Run 1 1/2" hole and set 10' of 2 1/2" casing with 10' cement.
Run 3/4" hole and set 10' of 1 1/2" casing.
Run 1/2" hole to approximately 12' to test casing.
If productive will set 1 1/2" casing on packer and 1/2" cement.

ILLEGIBLE



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company A. J. ...

Address Farmington, New Mexico

By [Signature]

Title _____