


(SUBMIT IN TRIPLICATE)

Land Office Santa Fe

Lease No. NM 03547

Unit _____

Branch " "



UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 2, 1959

Well No. NM-4 is located 990 ft. from [N] line and 990 ft. from [E] line of sec. 33

NE 1/4 33
(1/4 Sec. and Sec. No.)

27N
(Twp.)

6W
(Range)

NMPN
(Meridian)

South Elmore Dakota

Rio Arriba

New Mexico

Monte Verde

(County or Subdivision)

(State or Territory)

The elevation of the derrick floor above sea level is 6686 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 10 A.M. - 5-29-59.

May 30, 1959 - TD 265'.

Cemented 10 3/4" 32.75# H-40 B rd casing at 262', w/190 sacks common cement, 1% calcium chloride.

Cement circulated.

Plug down at 6:45 A.M., 5-30-59.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Caulkins Oil Company

Address P. O. Box 967

Armington, New Mexico

By Frank Gray
Title Field Superintendent