	UNITED STATES	5.	LEASE	有 50 克達	,	5	
DEI	PARTMENT OF THE INTERIOR		NM-0354	_• 7			
GEOLOGICAL SURVEY			6. IF INDIAN, ALLOTTEE OR TRIBE NAME				
<u> </u>		 		- 1 3 3 W	C	<u> </u>	
SUNDRY NO	OTICES AND REPORTS ON WELLS	7.	UNIT AGR	EEMENT NA	ME	· · · · · · · · · · · · · · · · · · ·	
	for proposals to drill or to deepen or plug back to a different 331–C for such proposals.)				<u> </u>	<u> </u>	
reservoir, Use Form 9–3	331–C for such proposals.)	_ 8.		LEASE NAM	E 🚆	2.5 <u>5</u>	•
1. oil ga	as ell K other			$\mathbf{F}^{\tilde{0}}$	- 1	<u> </u>	
well LJ we	ell KI other	9.	WELL NO.	6 H 2 H			
2. NAME OF OPE	ERATOR		12	<u> </u>	<u> </u>	<u> </u>	_
Caulkins Oil Company			10. FIELD OR WILDCAT NAMEBlanco-Mesa				
3. ADDRESS OF OPERATOR			South Blanco-Pictured Cliffs				
P.O. Box 780, Farmington, New Mexico			SEC., T., 1	R., M., OR B	LK. AN	D SURVEY OR	
4. LOCATION OF	WELL (REPORT LOCATION CLEARLY. See space 17	1	AREA	24 de 1998	9	동물리를	
below.)			Section	1 35 527	N 61	V ≨633	
	990' F N/L and 990' F E/L			OR PARISH			
AT TOP PROD.	Danie	F	Rio Arri	Lbă 💥 📆	New		
AT TOTAL DEP	Same	14.	API NO.	tenin og Jav sile ti udt nu	Ξ.	do 4 thungit the contraction of the	
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,				문화를	्र	£227	
REPORT, OR C	ATAC	15.				DB, AND WD))
			•	6608.'-Gr	• ગુર	를 높이 3	
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:				JU13	25	्रें <u>के दे</u> द	
TEST WATER SHUT-OFF				6 L 2 L	57	F283	
FRACTURE TREAT				- 青草草質	a d	<u> 원통설립</u>	
REPAIR WELL.			OTE: Basar	÷ č ≤ j receite de mu	ુ Itinla as		_
PULL OR ALTER CASING			(NOTE: Report results of multiple completion or zone change on Form 9–330.)				
MULTIPLE COMPLE			-	တာသည်။ သည်	75	연방률수 등	
CHANGE ZONES			:J		ü	g5.	- -
ABANDON*			***	- E & F E	n ojbui	13 a 7 0 1 3	•
(other) Comming	<u>gle Mesa Verde and Pictured Cliffs</u>				II. .≠		 ,
17 DECOMPE DD	OPOSED OR COMPLETED OPERATIONS (Clearly star	to all	nertinent c	hat elicted	give n	ertinent dates	•
including estim	nated date of starting any proposed work. If well is o	directio	onaliv drille	ed. give sub	surface	locations and	i
measured and	true vertical depths for all markers and zones pertine	nt to tl	his work.)*	1922	<u>ئ</u> ند	그 왕국 등	
					25	5 5 7 9	
6-2-79	Pulled 2 3/8" tubing and salvage	some	Ran	1 1/4" E	UE jti	ubing to	
	5539 '.			S 2 2 3 4	<u></u>	2001 2001 2001 2001 2001 2001 2001 2001	
				3 = 3 3 3	ေ၁င	24 g 100 100 100 100 100	
6-27-79	On line to Gas Company of New Mex	ico p	produci	ng at ra	te o	f 389	
	MCFPD.			1000 1000 1000 1000 1000 1000 1000 100	ንካር	三十五百百 一	
				40000	3113	₹ # # \$ / ()	

psadus bins llevi sindigitudis de dispendid includi in plicable State requirer for instructions. Subsurface Safety Valve: Manu. and Type ____

18. I hereby certify that the foregoing is true and correct

quil TITLE Superintendent 7-27-79 DATE

(This space for Federal or State office use)

APPROVED BY ______CONDITIONS OF APPROVAL, IF ANY:

DATE

JUL 3 1 1979

, 5

U. S. GEOLOGICAL SURVEY

DURANGO, COLO.

*See Instructions on Reverse Side