NEW MEXICO
OIL CONSERVATION COMMISSION

6/7/57

PACKER LEAKAGE TEST

OPERATOR El Paso
LEASE NAME San Juan Unit WELL NO. 27-5 #30
LOCATION 35-27-5 COUNTY Sa

TEST DATA SHEET

Time	Casing Pressure	Tubing Pressure	Remarks
	1019	1072	Shut in
11:20	1021	311	
11:35	1020	236	
11:50	1021	200	
12:05	1021	181	
1:05	1021	143	
2:05	1022	128	Tested by Mr. Buck
			Wit - Sa