

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. 079367-A  
Unit Rincon Unit

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

OCT 19 1959

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 120(40) is located 500 ft. from S line and 1050 ft. from W line of sec. 7  
in Sec. 7 (1/4 Sec. and Sec. No.) 27N (Twp.) 07 (Range) T.M.P.N. (Meridian)  
Alamo N.V. & Wildcat Dev. (Field) Alamo (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6035 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

Spud date 9-29-59.

On 10-2-59 Total Depth 320'.

Ran 10 joints, 13 3/8", 40#, 8-40 casing (307') set at 317' with 230 sacks regular cement, 114 cu. ft. Strata-Crete 70, 2 1/2 Gal, 2 1/2 Calcium Chloride circulated to surface.

Held 500#, 30 minutes.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company

Address Box 557

Farmington, New Mexico

By Original Signed D. W. Mehan  
Title Petroleum Engineer