



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office Santa FeLease No. 080670Unit San Juan 27-4 Unit
14-08-001-1054

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	Water Frac.	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 23, 1960Well No. 25 is located 600 ft. from SW line and 1100 ft. from EW line of sec. 30S.W. Sec. 30
(¼ Sec. and Sec. No.)27-N
(Twp.)4-W
(Range)N.M.P.M.
(Meridian)Blanco Mesa Verde
(Field)Rio Arriba
(County or Subdivision)New Mexico
(State or Territory)The elevation of the derrick floor above sea level is 6760 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On 10-15-60 Total Depth 5944'. C.O.T.d. 5905'.
Water frac Point Lookout perf int. 5772-5794; 5800-5812; 5820-5832; 5862-5868;
5877-5881 (2 SPP) w/76,985 gal water & 60,000 # sand. BDP none, max pr 1600 #,
avg tr pr 1400-1500-1600 #. I.R. 70 BPM. Flush 11,466 gal. Dropped 5 sets of
17 balls each.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas CompanyAddress Box 990Farmington, New MexicoBy Original Signed By: O.H. OlsonTitle Petroleum Engineer