



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office Santa FeLease No. 080570Unit San Juan 27-4 Unit
14-08-001-1074

SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED
JUL 18 1958

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	
	<u>Water Frac.</u> <u>X</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 14, 1958Well No. 17(PM) is located 810 ft. from N line and 1150 ft. from E line of sec. 21

<u>SW</u>	<u>Sec. 29</u>	<u>27E</u>	<u>4</u>	<u>N.M.P.M.</u>
($\frac{1}{4}$ Sec. and Sec. No.)		(Twp.)	(Range)	(Meridian)
<u>Blanco M.V. - Capemito</u>	<u>Rio Arriba</u>	<u>New Mexico</u>		
(Field)	(County or Subdivision)	(State or Territory)		
<u>P.C. Ext.</u>				

The elevation of the derrick floor above sea level is 6820 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

7-13-58. Total Depth 5986'. C.O.T.D. 5956'. Water fractured Point Lookout perf. int. (2 dyna jets/ft.) 5768-5784; 5818-5846; 5855-5872; 5884-5904; 5922-5948 with 63,000 gallons water and 65,000# sand. B.D.P. 1700#, max. pr. 3000#, avg. tr. pr. 2200#. I.R. 58.1 B.P.M. Flush 9800 gallons. Dropped 4 sets of 35 balls each and one set of 20 balls each for 5 stages.

7-13-58. Total Depth 5986'. Temporary Bridge Plug at 4015'. Water fractured Pictured Cliffs perf. int. (4 dyna jets/ft.) 3650-3674; 3690-3716 with 38,500 gallons water and 40,000# sand. B.D.P. 2200#, max. pr. 2100#, avg. tr. pr. 1700#. I.R. 67 B.P.M. Flush 7600 gallons. Dropped 3 sets of 50 balls each for 4 stages.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas CompanyAddress Box 977
Farmington, New Mexico

Original Signed D. C. Johnston

By _____

Title Petroleum Engineer