
Form 9-881 a
(Feb. 1951)



## (SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	ente Fe
Lease No	1793 <u>k</u>
Unit Rincon	this

GEOLO	OGICAL SURVEY
SUNDRY NOTICES A	ND DEDORMS on
SUNDR'I NOTICES A	AND REPORTS ON WELLS
NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING.
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALIER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	Water Frac. X
(INDICATE ABOVE BY CHECK MARK	C NATURE OF REPORT, NOTICE, OR OTHER DATA)
	Sovember 27, , 19 61
	1. ${S \atop S}$ line and $300$ ft. from ${W \atop W}$ line of sec. 29
S.W. Section 29 27-18 (% Sec. and Sec. No.) (Twp.)	N.M.P.M. (Range) (Meridian)
So. Danco Pictured Cliffs Rio (County o	
he elevation of the derrick floor above sea lev	(
	LS OF WORK
	es, weights, and lengths of proposed casings; indicate mudding jobs, cement- ther important proposed work)
Perf Pictured Cliffs intervals 3186- Water frac v/33,200 gal water contain plus 2% FR-2/1000 gal, and 25,000% a water. HDP 3050%, max pr 4000%, tr 1 14.9 BPM. Dropped 2 sets of 16 ball	-90;3218-20;3230-38; Ining 1% calcium chloride sand. Flush w/900 gal
	KLULITE
	DEC 4 1961 OIL CON. COM. DIST. 3
I understand that this plan of work must receive approval in w	writing by the Geological Survey before operations may be commenced.
ompany El Paso Matural Gas Company	
ddress Box 990	
Farmington, New Mexico	By Land of Control of State
	Title Petroleum Engireer

320 8 620 40