

(SUBMIT IN TRIPLICATE)

Land Office Santa Fe  
Lease No. 079367  
Unit San Juan 27-5 Unit  
14-G-001-950

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	<b>RECEIVED</b> <b>MAY 29 1958</b> <b>U.S. GEOLOGICAL SURVEY</b> <b>FARMINGTON, NEW MEXICO</b>	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 34 is located 1090 ft. from S line and 590 ft. from W line of sec. 30  
Sec. 30 (Sec. and Sec. No.) 27N (Twp.) 5W (Range) N.M.L.M. (Meridian)  
Blanco Rv (Field) Rio Arriba (County or Subdivision) New Mexico (State or Territory)  
& So. Blanco I. C. Ext.

The elevation of the derrick floor above sea level is 6406 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

3-26-58 Total depth 3447'.  
 Run 51 joints 5 1/2", 15.50#, J-55 liner (2210') set from 3221'  
 to 3439' with 125 sacks regular cement, 125 sacks romax, 6'  
 gel, followed by 90 sacks regular cement.  
 Held 1000# for 30 minutes.  
 Top of cement by temperature survey at 3221'.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Al Paso Natural Gas Company  
 Address Box 797  
Farmington, New Mexico  
 By Original Signed D. C. Johnston  
 Title Petroleum Engineer