REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL

PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES


## UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Form 9–331 Dec. 1973	Form Approved. Budget Bureau No. 42–R1424
UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	080385
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	Rincon Unit
	8. FARM OR LEASE NAME
1. oil gas X other	Rincon Unit
	9. WELL NO.
2. NAME OF OPERATOR	37
El Paso Natural Gas Company	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	South Blanco Pictured Cliffs
P.O. Box 289, Farmington, New Mexico 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA
below.)	Sec. 26, T-27-W, R-7-W PM
AF SURFACE: 1784'S, 1649'W, Sec. 26, T-27-N,	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: R-7-W	Rio Arriba New Mexico
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	6715 D.F.

(NOTE: Report results of full place appletion or zone change on form ==330.)

U. S. GEOLOGICAL SURVIK & GEOLOGICAL SURVEY ABANDON\* FARMINGTON, N. M. (other) 17. DESCRIBE PROPOSED OR COMPLETED OPER ATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

On February 2, 1982 the 1" tubing in this well was pulled, and bad tubing replaced. The new tubing T.D. is now 3107.50'.



**NMOCC** 

\*See Instructions on Reverse Side

FARMINGTON DISTRICT