



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 079364
Unit Rincon Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

November 16, 1959

Well No. 12800 is located 1600 ft. from S line and 900 ft. from W line of sec. 20
SW/4 Sec. 20 27N 6E S.M.T.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Blanco MV & Wilcox Dakota Rio Arriba New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6600 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On 11-12-59 Total Depth 7769'.
Run 14 joints 5", JJ-55, 15# liner (476') set from 7311' to 7767' w/60
sacks Pozmix 140.

Held 1000g/30 minutes

Top of cement by temperature survey at 7311'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Al Paso Natural Gas Company

Address Box 997

Farmington, New Mexico

By Original Signed R. G. MILLER

Title Petroleum Engineer