

**(SUBMIT IN TRIPLICATE)**

Indian Agency ----- ~~2100~~

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Allottee ~~Jicarilla Apache~~

Lease No. Contract 233

		X	

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

**February 26**-----, 19**63**

Well No. Apache 0-17 is located 660 ft. from N line and 1980 ft. from E line of sec. 17

SW/4 SE/4 Sec. 17      27N      1E      N.M.P.M.  
(1/4 Sec. and Sec. No.)      (Twp.)      (Range)      (Meridian)

**Undesignated** **Rio Arriba** **New Mexico**  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is ~~6979~~ ft.


## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate any down hole cementing points, and all other important proposed work)

10-10-62 Spotted.

10-21-62 Drilled to TD 2826'. Ran 7" casing to 1747'.

Well is now on pumping test.



RECEIVED

150 1000

U. S. GEOLOGICAL SURVEY  
WATER RESOURCES DIVISION

**I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.**

Company BINSON-MONTIN-GREE DRILLING CORP.

Address 158 Petroleum Center Building

**Farmington, New Mexico**

B.

Title Engineer