


(SUBMIT IN TRIPPLICATE)

Indian Agency Marilla School  
Center: PA, Box 110

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Allottee \_\_\_\_\_  
Lease No. Marilla 90



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 22, 1952

Well No. 6 is located 990 ft. from N line and 990 ft. from E line of sec. 27

NE 1/4 NE 1/4 Sec. 27 (1/4 Sec. and Sec. No.)  
27N 3W (Twp.) R. 1, P. 1 (Range) E. X. P. X. (Meridian)  
Marion NW & Undersig. 70 (Field) Rio Arriba (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 762 ft. G.L.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Set 175' of 7-1/8" Cas. @ 490', cemented w/75 lbs. 6 1/2 gal + 1/2 Flueoil sl. + 30 sls. mud. Plug down 1200 PM, September 20, 1952. Log cement @ 3000 by Temperature Survey. 100 24 hours. Setted 7-1/8" Cas. w/600' for 30 minutes, hold 61.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Magnum Petroleum Company

Address P. O. Box 2406

Marilla, New Mexico

By [Signature]

Title District Superintendent