GPO 862040

Form	9-88	11 B.
(Feb	. 1951)
Γ		

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Land Office	Santa Fe
Lease No	075365-A
Unit	Rincon

SUNDRY NOTICES	AND REPORTS ON WELLS
NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF ALTERING CASING SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR SUBSEQUENT REPORT OF ABANDONMENT NOV 15
NOTICE OF INTENTION TO ABANDON WELL.	U. S. GEOLOGICAL SURVEY
(INDICATE ABOVE BY CHECK MA	IRK NATURE OF REPORT, NOTICE, OR OTHER DATA)
	November 13, , 1961
	om $\left\{S\right\}$ line and 1650 ft. from $\left\{W\right\}$ line of sec. 23
S.W. Section 23 27-N (% Sec. and Sec. No.) (Twp.)	6-W N.M.P.M.
So. Blanco Pictured Cliffs Rio	triba New Mexico y or Subdivision) (State or Territory)
The elevation of the derrick floor above sea	
DET .	AILS OF WORK
(State names of and expected depths to objective sands; show: ing points, and a	sizes, weights, and lengths of proposed casings; indicate mudding jobs, cement- ll other important proposed work)
On 11-3-61 Total Depth 3396'. Ran casing (3384') set at 3394' with 19 1/4 cu. ft. Strata-Crete"6"/sk.	110 Joints 2 7/8". 6.4# J-55
Held 1500#/30 minutes.	ALTINED
	NOV 1 6 1961
	2451.3
I understand that this plan of work must receive approval company R1 Paso Natural Gas company	in writing by the Geological Survey before operations may be commenced.
Address Box 990	
Farmington, New Mexico	ByBy
	Title Petroleum Engineer