submitted in lieu of Form 3160-5

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT



| | | <u> </u> | |
|--|----------------------------------|---|--|
| Sundry Noti | ces and Reports on Wells | | |
| | 99 JUN 22 PM 12 | : 42 5. | Lease Number |
| 1. Type of Well GAS | 070 FARMAR 3701 | | SF-079492B If Indian, All. or Tribe Name |
| | | 7. | Unit Agreement Name |
| 2. Name of Operator | The same | The second second | |
| BURLINGTON | | | · · · · · · · · · · · · · · · · · · · |
| OIL OIL | GAS COMPANY | ε. Ω | San Juan 27-5 Unit Well Name & Number |
| 3. Address & Phone No. of Operat | or /EUE | TIPIN | San Juan 27-5 U #74 |
| PO Box 4289, Farmington, NM | 87499 (505) 326-9700 //// | 9.7 | API Well No. |
| 4. Location of Well, Footage, Se | ac., T, R, M (1)//r; | 1999 10. | 30-039-06955 Field and Pool |
| 890'FSL, 1650'FEL, Sec.23, T- | | _ | Tapacito Pict.Cliffs |
| \mathcal{O} | Rose To | | County and State Rio Arriba Co, NM |
| | | 700 | RIO AFFIDA CO, NM |
| 12. CHECK APPROPRIATE BOX TO INI | | RT, OTHER | DATA |
| Type of Submission Notice of Intent | Type of Action Abandonment Char | nge of Pla | ans |
| | Recompletion New | Construc | tion |
| _X_ Subsequent Report | | Routine : er Shut o | Fracturing ff |
| Final Abandonment | | | o Injection |
| 13. Describe Proposed or Compl | leted Operations | | |
| 5-19-99 TIH w/2 7/8" RBP, min, failed. TI RBP to slide do Release pkr, TO 5-20-99 Blow well & CO to 5-24-99 MIRU. Pump 200 ga | CO. | DH. PT cso Scale but ve RBP. F tch RBP, NU WH. R sting Pic | g to 3700 psi/15 ild up on csg caused T csg to 500 psi, OK. TOOH. TIH. SDON. D. Rig released. tured Cliffs perfs |
| | Title | Date _ | |
| the United States any false, fictitious or fr | | | |

NMOCD