

Section 22

(SUBMIT IN TRIPLICATE)

Indian Agency McKsville Tribal

Contract 94 Tr. 153

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____

Lease No. McKsville #7

SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED
JUL 1 1957
OIL SURVEY
MEXICO

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 27, 1957

Well No. 3 is located 990 ft. from S line and 990 ft. from W line of sec. 22

Sec. 22 Range 34 Twp. 27-N M. 1-E
(Sec. and Sub. No.) (Range) (Meridian)


Blanco McKsville Tex. Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 7142 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

After setting 4380' of 7-5/8" Intermediate Casing on bottom at 4380' with 100 cc cement, Temperature survey @ 3610'. Tested 7-5/8" Intermediate Casing with 1200 lbs for 30 minutes before and after drilling plug. Tested OK. No break.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company McKsville Petroleum Company

Address P.O. Box 603

McKsville, Texas

By Harve H. Mayfield

Title HARVE H. MAYFIELD
Asst. Division Superintendent

