

(SUBMIT IN TRIPLICATE)

Indian Agency Navajo TribalContract / 94, Tr. 103

Allottee _____

Lease No. Navajo 77UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

07			

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 10, 1957

Well No. 3 is located 990 ft. from S line and 990 ft. from W line of sec. 22Sec. 22
(1/4 Sec. and Sec. No.)27-N
(Twp.)3-W
(Range)N.M.S.M.
(Meridian)Blanco
(Field)Rio Arriba
(County or Subdivision)New Mexico
(State or Territory)The elevation of the derrick floor above sea level is 7162 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

After setting 2125' of 5 1/2" Liner on bottom at 6340' with 200 cu cement. Temp. survey top of Cement at 4132'. Drilled out cement inside Liner to 4290'. Tested with 1900 lbs for 30 minutes. tested OK. No break.



RECEIVED
JUL 16 1957
U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company NAJAVIA PETROLEUM COMPANYAddress P.O. BOX 693KINLAND, TEXASBy [Signature]
Title Division Superintendent

