


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 07-640
Unit San Juan 20-7
14-00-001-477



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 20 is located 1112 ft. from N line and 1050 ft. from E line of sec. 21

Sec. 21 (1/4 Sec. and Sec. No.) 27N (Twp.) 7N (Range) N.M.P.M. (Meridian)
So. Blanco P. Co. (Field) San Arriba (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6532 ft.


DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

2-4-58 Total depth 3050'.
Ran 93 joints 5 1/2", 17.50#, J-55 casing (3030.71') set at 3040.71' with
50 sacks regular cement, 50 sacks rosinix, 25 gal, followed by 50 sacks
regular cement.

Held 1000' for 30 minutes.

Top of cement by temperature survey at 1000'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company

Address Box 997
Paradise, New Mexico

Original Signed D. C. Johnston

By _____

Title Petroleum Engineer