COMPANDA POR

LINUTED OTATED			
UNITED STATES	5. LEASE SF 079403		
DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepee or humber 1822 a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME San Juan 27-5 Unit		
1. oil gas Oil CON. COM.	8. FARM OR LEASE NAME San Juan 27-5 Unit 9. WELL NO.		
2. NAME OF OPERATOR El Paso Natural Gas Company	95 10. FIELD OR WILDCAT NAME		
3. ADDRESS OF OPERATOR P. O. Box 289, Farmington, N. M. 87401	Tapacito Pictured Cliffs 11. SEC., T., R., M., OR BLK. AND SURVEY O		
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 500'S & 100'W AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	AREA Sec. 15, T27N, R5W 12. COUNTY OR PARISH 13. STATE Rio Arriba New Mexico 14. API NO.		
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WE		
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* SUBSEQUENT REPORT OF: TEPORT OF: TEPOR	/ED (NOTE: Report results of multiple completion or zor L SURVEY Change on Form 9–330.)		

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

(other) Subsequent report of action being taken to abandon.

On November 11, 1980, an Otis Perma Lack packer was set on 1 1/4" tubing in this well in order to temporarily repair a casing failure.

Since that time the well has been swabbed on 5 separate operations bringing up only water and no gas. The well is not capable of production and has not produced since August of 1980. At present, a proposal to plug and abandon is being prepared and is awaiting approval.

Subsurface Safety Valve: Manu. and Typ	e		CCEPTED FOR RECORD Set @	Ft.
18. I hereby certify that the foregoing is SIGNED HOLD HOLD HOLD TO	true and correct Production	DATE _	JAN 12 1982	
	(This space for Federal or State office us		(3)	
APPROVED BY	TITLE	DATE		

NMOCC.