

(SUBMIT IN TRIPLICATE)

Land Office **Santa Fe**  
Lease No. **078840**  
Unit **San Juan 28-7 Unit**

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 13, 1961

Well No. **122** is located **790** ft. from **XXXX** line and **1850** ft. from **XXE** line of sec. **18**

**S.W. Section 18**  
(¼ Sec. and Sec. No.)

**27-N**  
(Twp.)

**7-W**  
(Range)

**N.M.P.M.**  
(Meridian)

**So. Blanco Pictured Cliffs**  
(Field)

**Rio Arriba**  
(County or Subdivision)

**New Mexico**  
(State or Territory)

The elevation of the derrick floor above sea level is **6550** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 7-8-61, On 7-9-61, total depth 105'.  
Ran 3 joints 8 5/8" 24#, J-55 casing (99') set at 105'.  
Cemented with 140 sacks regular. Circulate to surface.  
Held 1500#/30 minutes.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **El Paso Natural Gas Company**

Address **Box 990**

**Farmington, New Mexico**

By **ORIGINAL SIGNED A.M. SMITH**

Title **Petroleum Engineer**

(SUBMIT IN TRIPLICATE)

Land Office **Santa Fe**  
Lease No. **078840**  
Unit **San Juan 28-7 Unit**

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 25, 19 61

Well No. **122** is located **790** ft. from **S** line and **1850** ft. from **W** line of sec. **18**  
**S.W. Section 18** **27-N** **7-W** **N.M.P.M.**  
(¼ Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
**So. Blanco Pictured Cliffs** **Rio Arriba** **New Mexico**  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **6550** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On 7-21-61, Total Depth 2992'.  
Ran 101 joints 2 7/8" 4.7 J-55 casing  
(2981') set at 2991'. Cemented with 150 sacks HYE-400  
and 100 sacks regular, 2½ gal, 1/4 cu.ft. Strata-Crete "6"/sk.  
Held 1500#/30 minutes.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **El Paso Natural Gas Company**

Address **Box 990**

**Farmington, New Mexico**

Original Signed R. G. MILLER  
By

Title **Petroleum Engineer**