

Santa Fe

(SUBMIT IN TRIPLICATE)

Land Office

Lease No.

070640

Unit

San Juan 29-7 Unit

14-08-001-450

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 25, 1958

Well No. 32 (44) is located 1100 ft. from {S} line and 1100 ft. from {W} line of sec. 15

SW Sec. 15 27N 7W N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Blanco H.V. & So. Blanco I. Lo Arriba New Mexico
(Field) (County or Subdivision) (State or Territory)
P.C.

The elevation of the derrick floor above sea level is 6681 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

3-17-58. Total Depth 3355'.

Run 80 joints 7 5/8", J-55, 26.40#, casing (3344) set at 3354' with 50 sacks regular cement, 50 sacks Pozzix, 25 # Flocale and 25 #el, followed with 50 sacks Bent cement.

Held 1000# for 30 minutes.

Top of cement by temperature survey at 2100'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company

Address Box 997

Farmington, New Mexico

Original Signed D. C. Johnson

By

Title Petroleum Engineer