


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 079298
Unit Rincon Unit



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	<u>Water Frac.</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 20, 1962

Well No. 177 is located 50 ft. from 300 line and 190 ft. from 190 line of sec. 13

SW Section 13 (Sec. and Sec. No.) 27-N (Twp.) 7-W (Range) N.M.P.M. (Meridian)


Basin Docks (County or Subdivision) Rio Arriba (State or Territory) New Mexico

The elevation of the derrick floor above sea level is 72 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

On 8-17-62, T.D. 7780'. C.O.T.D. 7720'.
Perf 7688-92; 7648-54; (2 SPF); 7554-58; 7538-42; 7526-30 (3 SPF);
Frac w/83,000 gallons water, 80,000# sand. Flush w/4800 gal.
I.R. 36.5 BPM. Max pr 3750#, BDP 3000#, tr pr 3000-3750#. 4 drops
of 12 balls.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company R. Paso Natural Gas Company

Address Box 990

Farmington, New Mexico

By Original Signed D. W. Meehan

Title Petroleum Engineer