



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.
Form Approved.

Land Office Santa Fe
87030

Lease No. _____

Unit Rincon Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 147 is located 1100 ft. from N line and 1650 ft. from E line of sec. 13
27-N 7-E N.M.P.M.
(Twp.) (Range) (Meridian)

NE Section 13 New Mexico
(1/4 Sec. and Sec. No.) (State or Territory)
Basin Dakota El Arriba
(Field) (County or Subdivision)

The elevation of the derrick floor above sea level is 6550 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spud date 6-27-62, On 6-29-62 T.D. 320'. Ran 20 lbs. 9 5/8"
11-40, 32.25 (300') set at 319'. Cemented w/210 sacks regular,
3/4 cu. ft. Strata-Crete 6"/sk., 25 A-4. Circulated to surface.
Hold 600/30 minutes.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company

Address Box 990
Farmington, New Mexico

By Original Signed D. W. Meehan
Title Petroleum Engineer