

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

| Land Office | Sente Fe |
|-------------|----------|
| Lease No. | 079398 |

Unit San Auen 27-5 Unit

GPO 862040

| SUNDRY NOTICES | S AND REPORTS ON WELLS |
|---|--|
| NOTICE OF INTENTION TO DRILL | SUBSEQUENT REPORT OF WATER SHUT-OFF |
| NOTICE OF INTENTION TO CHANGE PLANS | |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF | SUBSEQUENT REPORT OF ALTERING CASING. |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL | SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE | SUBSEQUENT REPORT OF ABANDONMENT |
| NOTICE OF INTENTION TO PULL OR ALTER CASING | SUPPLEMENTARY WELL HISTORY |
| NOTICE OF INTENTION TO ABANDON WELL | |
| (INDICATE ABOVE BY CHECK | MARK NATURE OF REPORT, NOTICE, OR OTHER DATA) |
| | July 25, , , 1961 |
| Well No. 65 is located 890 ft. f | from \(\bigcirc \) line and \(\bigcirc \) ft. from \(\bigcirc \) line of sec. \(\bigcirc \) 17 |
| N.R. Section 17 27-H | 5-4 R.H.P.M. |
| (1/4 Sec. and Sec. No.) (Twp.) | (Range) (Meridian) |
| Tapacito P. C. Bet. Rio A | ounty or Subdivision) (State or Position) |
| Spudded 7-19-61. On 7-80-61 Total Depth 109'. Ren 3 joints 8 5/8" 34 J-55 cast set at 109. Commuted with 160 and to surface. Rel4 6005/30 misurtes. | cks remise. Circulated |
| I understand that this plan of work must receive approva | al in writing by the Geological Survey before operations may be commenced. |
| | |
| | |
| | |
| ompany El Paso Mataral Gas Comp | Original Signed R. G. MILLER By |