UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Danaz j	ces and Reports on Wells	21
Type of Well GAS		5. Lease Number SF-079363 6. If Indian, All. or Tribe Name Unit Agreement Name
Name of Operator RESOURCES OIL 8 Address & Phone No. of Operat PO Box 4289, Farmington, NM Location of Well, Footage, Se 890'FSL, 990'FWL, Sec.10, T-2	87499 (505) 326-9700 0000 ec., T, R, M	San Juan 28-6 Unit Well Name & Number San Juan 28-6 U #25 9. API Well No. 30-039-07098 10. Field and Pool Blanco Mesaverde 11. County and State Rio Arriba Co, NM
. CHECK APPROPRIATE BOX TO INITYPE of Submission Notice of Intent X Subsequent Report Final Abandonment	Abandonment Ch Recompletion Ne Plugging Back Ne Casing Repair We Altering Casing Co X Other - Tubing repair	nange of Plans ew Construction
WH, no seconda 12-7-99 TIH w/5 ½" RBP & OK. Load hole of SDON.	ekend. TIH, tag PBTD @ 5540'. TOOH ry seal. SDON. a pkr; set RBP @ 4700', set w/100 bbl 2% KCl wtr. PT cs	pkr @ 4670'. PT RBP to 1000 psi, g to 1000 psi, OK. Blow well & C J-55 EUE tbg, landed @ 6565'.
4. I hereby certify that the	e foregoing is true and corr	cect. Lstrator Date 12/9/99

DEC+1 5 1999