

El Paso Natural Gas Company
ANNUAL PACKER LEAKAGE TEST

Form 20-150B (Rev. 9-57)

El Paso Natural Gas Company

Date 4/23/59

San Juan 28-6 No. 81 (PM)

Unit M

Location 12-27-6

County Rio Arriba

Pictured Cliffs, Mesa Verde

Gas/Gas

Dual Completion

UPPER COMPLETION

LOWER COMPLETION

DATE	PRESSURE	Shut In	Pictured Cliffs Formation	Shut In	Mesa Verde Formation
3/13/59	479	3/6/59	3/13/59	3/6/59	3/13/59
			S IPT		S IPT
			479		838

DATE	Shut In	Flowing	Shut In
3/20/59	536	3/13/59	523

DATE	Shut In	Flow Rate = 176 MCF/D	Shut In
3/27/59	583	3/20/59	833

DATE	Flowing	Shut In	Flowing
3/31/59	508	3/27/59	845
4/3/59	493	4/3/59	852

Flow Rate = 744 MCF/D

Remarks:

This well (may) ~~be~~ be produced as desired.

No

The results of this test indicate ~~no packer leakage~~ (Packer Leakage) in this well.

All pressures were taken with a dead weight gauge.

A graph is attached hereto showing pressures of each zone plotted against time.

I hereby certify that the information herein contained is true and complete to the best of my knowledge.

Approved: 4-29-59

New Mexico Oil Conservation Commission

By: *Emery C. Amos*
Supervisor Dist. # 3

By: *Tom B. Grant*
Tom B. Grant
Gas Engineer

