

NORTHWEST NEW MEXICO PACKER-LEAKAGE TEST

Operator	BURLINGTON RESOURCES OIL & GAS CO.				Lease	SAN JUAN 28-6 UNIT		Well No.	79	
Location of Well:	Unit	M	Sect	11	Twp.	027N	Rge.	006W	County	RIO ARRIBA
	NAME OF RESERVOIR OR POOL				TYPE OF PROD. (Oil or Gas)		METHOD OF PROD. (Flow or Art. Lift)		PROD. MEDIUM (Tbg. or Csg.)	
Upper Completion	PICTURED CLIFFS				Gas		Flow		Tubing	
Lower Completion	MESAVERDE				Gas		Flow		Tubing	
PRE-FLOW SHUT-IN PRESSURE DATA										
Upper Completion	Hour. date shut-in	Length of time shut-in			SI press. psig		Stabilized? (Yes or No)			
	06/06/2000	72 Hours			563					
Lower Completion	06/06/2000	120 Hours			407					
FLOW TEST NO. 1										
Commenced at (hour.date)*	06/09/2000			Zone producing (Upper or Lower)			UPPER			
TIME	LAPSED TIME	PRESSURE			PROD. ZONE					
(hour.date)	SINCE*	Upper Completion	Lower Completion		TEMP		REMARKS			
6/10/200	96 Hours	145	423				turned on pc			
6/11/200	120 Hours	155	450							
Production rate during test										
Oil:	BOPD based on		Bbls. in		Hours.		Grav.		GOR	
Gas:	MCFPD; Tested thru (Orifice or Meter):									
MID-TEST SHUT-IN PRESSURE DATA										
Upper Completion	Hour. date shut-in	Length of time shut-in			SI press. psig		Stabilized? (Yes or No)			
Lower Completion	Hour. date shut-in	Length of time shut-in			SI press. psig		Stabilized? (Yes or No)			

5343801 307

(Continue on reverse side)



