


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Santa Fe**
Lease No. **079391**
Unit **San Juan 27-5**



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 27, 19 **62**

Well No. **86** is located **1190** ft. from **XIX** line and **550** ft. from **XIX** line of sec. **9**

SW Section 9 **R7-N** **S-W** **N.M.P.M.**
(¼ Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Basin Dakota **Rio Arriba**
(Field) (County or Subdivision)

RECEIVED

The elevation of the derrick floor above sea level is **6737** ft.

OCT 1 1962

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate points, and all other important proposed work)

Spud date 9-7-62, on 9-7-62 T.D. 328'.
Run 10 jts. 16 3/4" E-40, 32.75' (313') set at 327'.
Cemented w/30 sacks regular, 1/4 cu. ft. Strata-Crete "6"/sk. 25 M-5.
Circulated to surface. Held 600#/30 minutes.

U.S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

El Paso Natural Gas Company

Company **Box 990**

Address **Farmington, New Mexico**

By **ORIGINAL SIGNED H.E. McANALLY**

Title **Petroleum Engineer**