

Section 11

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R359.4
Approval expires 12-31-60.

Indian Agency Jicarilla Tribal

Contract / 89, Tr. 178

Allottee _____

Lease No. Jicarilla "E"

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

RECEIVED
OCT 3 1957
U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 1, 1957

Jicarilla "E"
Well No. 4 is located 990 ft. from [M] line and 990 ft. from [E] line of sec. 11

SW 1/4 Sec. 11 27-N 3-W N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Blanco M.V. Pk. Cliff El Arribe New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6269 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)


After setting 295' of 10-3/4" Surface Casing on bottom at 295' with 250 cc cement. Circulated. Tested 10-3/4" Surface Casing with 500 # for thirty minutes before and after drilling plug. Tested OK. No break.

I understand that this plan of work must receive approval in writing by the Geological Survey before operation may be commenced.

Company MAGNOLIA PETROLEUM COMPANY

Address P.O. BOX 633

MIDLAND, TEXAS



By R.T. GERMAN
Title Division Superintendent