

This form is not to
be used for reporting
packer leakage tests
in Southeast New Mexico

NORTHWEST NEW MEXICO PACKER-LEAKAGE TEST

Operator MOBIL PRODUCING TR. & N.M. INC. Lease Jicarilla E Well No. 4
Location of Well: Unit M Sec. 11 Twp. 27 N Rge. 03 W County Rio Arriba

	NAME OF RESERVOIR OR POOL	TYPE OF PROD. (Oil or Gas)	METHOD OF PROD. (Flow or Art. Lift)	PROD. MEDIUM (Tbg. or Csg.)
Upper Completion	Bavilan Pictured Cliffs	Gas	Flow	Tbg.
Lower Completion	Blanco Mesa Verde	Gas	Flow	Tbg.

PRE-FLOW SHUT-IN PRESSURE DATA

	Hour, date shut-in	Length of time shut-in	SI press. psig	Stabilized? (Yes or No)
Upper Completion	12:30 12-23-90	3 Days	679#	Yes
Lower Completion	12:30 12-23-90	3 Days	494#	Yes

FLOW TEST NO. 1

Commenced at (Hour, date) # 12-28-90		Zone producing (Upper or Lower) LOWER				
TIME (Hour, date)	LAPSED TIME SINCE #	PRESSURE		PROD. ZONE TEMP.	REMARKS	
		Upper Completion	Lower Completion			
12-29-90	1 Day	693#	331#	Date	12-26-90	12-27-90
12-30-90	2 Day	694#	464#	Upper	693#	693#
				Lower	504#	493#

Production rate during test

Oil: _____ BOPD based on _____ Bbls. in _____ Hours. _____ Grav. _____ GOR _____

Gas: _____ MCFPD; Tested thru (Orifice or Meter): _____ METER

MID-TEST SHUT-IN PRESSURE DATA

	Hour, date shut-in	Length of time shut-in	SI press. psig	Stabilized? (Yes or No)
Upper Completion				
Lower Completion				

RECEIVED

MAY 10 1991

OIL CON. DIV.

(Continue on reverse side)