

This form is not to
be used for reporting
packer leakage tests
in Southeast New Mexico

NORTHWEST NEW MEXICO PACKER-LEAKAGE TEST

Operator MOBIL PRODUCING TK. & N.M. INC. Lease Jicarilla E Well No. 4
Location of Well: Unit M Sec. 11 Twp. 27N Rge. 03W County Rio Arriba

	NAME OF RESERVOIR OR POOL	TYPE OF PROD. (Oil or Gas)	METHOD OF PROD. (Flow or Art. Lift)	PROD. MEDIUM (Tbg. or Csg.)
Upper Completion	Gavilan Pictuered Cliffs	Gas	Flow	TBG
Lower Completion	Blanco Mesa Verde	Gas	Flow	TBG

PRE-FLOW SHUT-IN PRESSURE DATA

	Hour, date shut-in	Length of time shut-in	SI press. psig	Stabilized? (Yes or No)
Upper Completion	11-9-91	29 days	369#	yes
Lower Completion	11-9-91	29 days	449#	yes

FLOW TEST NO. 1

Commenced at (hour, date)* <u>12-11-91</u>				Zone producing (Upper or Lower): <u>LOWER</u>		
TIME (hour, date)	LAPSED TIME SINCE*	PRESSURE		PROD. ZONE TEMP.	REMARKS	
		Upper Completion	Lower Completion			
12-12-91	1st day	359#	449#	date	12-9-91	12-10-91
12-13-91	2nd day	335#	449#	upper	369#	369#
				lower	449#	449#

Production rate during test

Oil: _____ BOPD based on _____ Bbls. in _____ Hours. _____ Grav. _____ GOR _____
Gas: 38 MCFPD; Tested thru (Orifice or Meter): METER

MID-TEST SHUT-IN PRESSURE DATA

	Hour, date shut-in	Length of time shut-in	SI press. psig	Stabilized? (Yes or No)
Upper Completion				
Lower Completion				

RECEIVED
DEC 30 1991
OIL CON. DIV
DIST. 3

(Continue on reverse side)

Packer--Leakage Test

Jicarilla E 4

