

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office San Antonio
Lease No. 079-91
Unit 20-4
14-0 -001-950-

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 1-11 is located 990 ft. from N line and 990 ft. from E line of sec. 11


2-7 (Twp.) 31 (Range) 14-0 (Meridian)
1-11 (Field) 14-0 (County or Subdivision) 14-0 (State or Territory)

The elevation of the derrick floor above sea level is 990 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Run to 400' on run 4367.80' of 7-5/8 O.D. 26.22 lb/ft. 4-5 1/2 in. cas. w/ Baker Drill Bit and float collar - Set at 436' w/ 100 lb 3/4 gal and 100 lb cement - 1:30 P.M. 1-29-56 - Tested cas. o.k. Drilled plug 7:00 a.m. 1-31-56.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company San Antonio Pipeline Corp.

Address San Antonio, Texas

By Original signed by T. A. Dugan

Title 1-trist engineer