Budget Bureau No. 42-R358.4. Approval expires 12-31-60. Form 9-381 a (Feb. 1951) - Pile Land Office (SUBMIT IN TRIPLICATE) UNITED STATES 3 DEPARTMENT OF THE INTERIOR A-001-1051 GEOLOGICAL SURVEY SUNDRY NOTICES AND REPORTS ON WELLS SUBSEQUENT REPORT OF WATER SHUT-OFF NOTICE OF INTENTION TO DRILL SUBSEQUENT REPORT OF SHOOTING OR ACID NOTICE OF INTENTION TO CHANGE PLANS..... NOTICE OF INTENTION TO TEST WATER SHUT-OFF..... SUBSEQUENT REPORT OF ALTERING CASING. NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR NOTICE OF INTENTION TO SHOOT OR ACIDIZE..... SUBSEQUENT REPORT OF ABANDONMENT. NOTICE OF INTENTION TO PULL OR ALTER CASING..... NOTICE OF INTENTION TO ABANDON WELL. (INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA) February 26, Well No. 75-3 is located 750 ft. from $\binom{N}{S}$ line and 1850 ft. from $\binom{E}{W}$ line of sec. 3 27 North I.H.P.M. (Twp.) (Meridian) see Verde Rio Arriba New Mexico (Field) (County or Subdivision) (State or Territory) above sea level is 6257 ft. The elevation of the DETAILS OF WORK (State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work) Pers 5374-78, 5304-08, 5288-92, 5276-86, 5262-70, 5250-58, 5232-42, 5186-5226, 5104-08, Free w/75,600 gals water. Used 240 rubber balls. Perr 5012-08, 4984-80, 4870-66, 4750-34, 4730-26, 4724-18, 4716-12, 4708-04, 4700-4686, 4682-78, 4674-70, 4668-64, 4656-32, 4626-20. Set Baker retr bridge plug 6 5060'. Frac w/78,000 gals water. Used 200 rubber balls. Rec bridge plug. Cleaned out to total depth. Set 5174.57' of 2" taking @ 5184.07' ... Completed well.