

EL PASO NATURAL GAS COMPANY
OPEN FLOW TEST DATA

DUAL COMPLETION

DATE October 20, 1959

Operator El Paso Natural Gas Company		Unit San Juan 28-7 Unit No. 102 (P)	
Location 9908, 1790W; 2-27-7		County Rio Arriba New Mexico	
Pictured Cliffs		South Blanco	
Casing Diameter 7-5/8	Perforations 3353	Casing Depth 1-1/4	Perforations 3212
Perforations 3170	Perforations 3208	Perforations 5605 c/o 5570	Shut In: 9/29/59
Sand Water Frac.		X	

Casing Diameter .75		Casing Depth 12.365		Casing Depth 5-1/2 liner 3301-5607	
Perforations 976 (PC)	Perforations 988	Perforations 21	Perforations 976 (PC)	Perforations 988	Perforations 988
Perforations 171	Perforations 183	Perforations 163	Perforations 163	Perforations 175	Perforations 175
Perforations 60	Perforations .85	Perforations 1.019	Perforations 1.019	Perforations .675	Perforations .675

Initial SIPT (MV) = 1036 psig
Final SIPT (MV) = 1039 psig

Packer at 4756

GROSS VOLUME = $Q \times C \times L \times F \times P \times T$

$$12.365 \times 183 \times 1.000 \times .9427 \times 1.019$$

2174

MCF/D

976144
945519

$$1.0323^{.85} \times 2174 = 1.0274 \times 2174$$

2234

MCF/D

S. V. Roberts



Lewis D. Galloway
L. D. Galloway