

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company El Paso Natural Gas Company		Address Box 990, Farmington, New Mexico				
Lease San Juan 28-7 Unit	Well No. 2	Well Letter K	Section 5	Township 27-N	Range 7-W	
Date Work Performed 1-24-63	Pool Blanco Mesa Verde			County Rio Arriba		

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
☒ Temporary Plugback
☐ Casing Test and Cement Job
☐ Remedial Work
☐ Other (Explain):

Detailed account of work done, nature and quantity of materials used, and results obtained:

1. Cut stuck tubing @ 4800'.
2. Spotted a 200 sack cement plug in open hole (4781'-5700').
3. Pulled tubing & bolted a dry hole marker on top of bradenhead flange.



Witnessed by	Position	Company
--------------	----------	---------

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

DOB Elev.	T.D.	FBH	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by Original Signed Emery C. Arnold	Name
Title Supervisor Dist. # 3	Position Petroleum Engineer
Date APR 23 1963	Company El Paso Natural Gas Company