

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Central Pa
Lease No. 7467
Unit 14-0-00-47

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 12 is located 1121 ft. from N line and 1150 ft. from E line of sec. 4
1121 (S)

1121 (1/4 Sec. and Sec. No.) 27N (Twp.) 7 W (Range) 1121.11 (Meridian)
1121.11 (Field) 1121.11 (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 5722 ft.


DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On February 4, 1950, Total depth 3471'.
Run 24 joints 7 5/8", 3-95, 20.44, Casing (3473.20') set at 3400' with 50 sacks regular cement, 50 sacks rommix, 20 Flocos and 20 Oil, followed with 50 sacks Best cement.

Hold 1000/30 minutes.

Top of cement by temperature survey at 2450'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company

Address 1001

Paragon, New Mexico

By Signed D. C. Johnston

Title Production Engineer