

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 copy to
appropriate
District Office
and 1 copy to
the Santa Fe Office

(Revised 3/9/94)

PIT REMEDIATION AND CLOSURE REPORT

Operator: _____ Conoco, Inc. _____ Telephone: _____		
Address: _____ 3315 Bloomfield Hwy. _____ Farmington, NM 87401 _____		
Facility Or: _____ San Juan 28-7 #44 _____		
Well Name _____		
Location: Unit or Qtr/Qtr Sec _____ A _____ Sec _____ 2 _____ T _____ 27N _____ R _____ 7W _____ County _____ Rio Arriba _____		
Pit Type: Separator _____ Dehydrator _____ Other _____ Tank Drain Pit _____		
Land Type: BLM _____, State _____ X _____, Fee _____ Other _____		
Pit Location: Pit dimensions: length _____ 6' _____, width _____ 6' _____, depth _____ 2' _____ (Attach diagram) Reference: wellhead _____ X _____, other _____ Footage from reference: _____ 90' _____ Direction from reference: _____ 168 _____ Degrees _____ X _____ East North _____ X _____ of _____ West South _____		
Depth To Ground Water (Vertical distance from contaminants to seasonal high water elevation of ground water.)	Less than 50 feet 50 feet to 99 feet Greater than 100 feet	(20 points) (10 points) (0 points) _____ 20 _____
Wellhead Protection Area: (Less than 200 feet from a private domestic water source, or; less than 1000 feet from all other water sources.)		Yes (20 points) No (0 points) _____ 0 _____
Distance To Surface Water: (Horizontal distance to perennial lakes, ponds, rivers, streams, creeks, irrigation canals and ditches.)	Less than 200 feet 200 feet to 1000 feet Greater than 1000 feet	(20 points) (10 points) (0 points) _____ 0 _____
RANKING SCORE (TOTAL POINTS): _____ 20 _____		



Date Remediation Started: _____		Date completed: _____	
Remediation Method: Excavation _____	Approx. cubic yards _____		
(Check all appropriate sections.)	Landfarmed _____	Insitu Bioremediation _____	
Other _____			

Remediation Location: Onsite _____ Offsite _____
(i.e. landfarmed onsite,
name and location of
offsite facility) _____

General Description of Remedial Action: _____
_____ none necessary _____

Ground Water Encountered: No ☒ Yes _____ Depth _____

Final Pit: Sample location _____ 3' below pit bottom _____
Closure Sampling: _____
(if multiple samples,
attach sample results
and diagram of sample
locations and depths) Sample depth _____ 5' _____
Sample Date _____ 11/13/2000 _____ Sample time _____ 10:00 AM _____

Sample Results

Benzene(ppm) _____ ND _____

Total BTEX(ppm) _____ .0258 _____

Field headspace(ppm) _____ 0.0 _____

TPH _____ 1.3 _____


Ground Water Sample: Yes _____ No ☒ (If yes, attach sample results)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Date

9/6/01

Signature



Printed Name
and Title

John Cofer, Environmental Director

ENVIROTECH LABS

PRACTICAL SOLUTIONS FOR A BETTER TOMORROW

EPA METHOD 8021 AROMATIC VOLATILE ORGANICS

Client:	Conoco Inc	Project #:	707003-263
Sample ID:	TDP	Date Reported:	11-14-00
Laboratory Number:	18557	Date Sampled:	11-13-00
Chain of Custody:	8305	Date Received:	11-13-00
Sample Matrix:	Soil	Date Analyzed:	11-14-00
Preservative:	Cool	Date Extracted:	11-13-00
Condition:	Cool & Intact	Analysis Requested:	BTEX

Parameter	Concentration (ug/Kg)	Det. Limit (ug/Kg)
Benzene	ND	1.8
Toluene	18.8	1.7
Ethylbenzene	ND	1.5
p,m-Xylene	ND	2.2
o-Xylene	7.0	1.0
Total BTEX	25.8	


ND - Parameter not detected at the stated detection limit.

Surrogate Recoveries:	Parameter	Percent Recovery
	Trifluorotoluene	100 %
	Bromofluorobenzene	100 %

References: Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA, December 1996.

Method 8021B, Aromatic Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846, USEPA, December 1996.

Comments: San Juan 28-7 #44. OVM 0.0


Analyst


Review

ENVIROTECH LABS

PRACTICAL SOLUTIONS FOR A BETTER TOMORROW

EPA METHOD 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons


Client:	Conoco Inc.	Project #:	707003-263
Sample ID:	TDP	Date Reported:	11-14-00
Laboratory Number:	18557	Date Sampled:	11-13-00
Chain of Custody No:	8305	Date Received:	11-13-00
Sample Matrix:	Soil	Date Extracted:	11-13-00
Preservative:	Cool	Date Analyzed:	11-14-00
Condition:	Cool and Intact	Analysis Requested:	8015 TPH


Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5 - C10)	ND	0.2
Diesel Range (C10 - C28)	1.3	0.1
Total Petroleum Hydrocarbons	1.3	0.1

ND - Parameter not detected at the stated detection limit.

References: Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846, USEPA, December 1996.

Comments: San Juan 28-7 #44. OVM 0.0


Analyst


Review

08305

Client / Project Name				Project Location		ANALYSIS / PARAMETERS									
Conoco Inc				San Juan 28-7 #44											
Sampler: J. Cofey				Client No. 707003-263											
Sample No./ Identification	Sample Date	Sample Time	Lab Number	Sample Matrix	No. of Containers	TPH	BTEX								Remarks
TDP	11/13/00	10:00	18557	Soil	1	✓	✓								OUM 0.0
BDP	11/13/00	10:25	18558	Soil	1	✓	✓								OUM 10
Relinquished by: (Signature) <i>J. Cofey</i>				Date	11/13/00	Time	12:15	Received by: (Signature) <i>Christa Welter</i>				Date	11-13-00	Time	12:15
Relinquished by: (Signature)								Received by: (Signature)							
Relinquished by: (Signature)								Received by: (Signature)							

ENVIROTECH INC.

5796 U.S. Highway 64
Farmington, New Mexico 87401
(505) 632-0615

Sample Receipt

Y

N

N/A

Received Intact


Cool - Ice/Blue Ice

Lease Name: San Juan 28-7 #44 MV

Operator: Bob Williams

Date: 2/01 2000

Site Security
(Indicate North)



Lease Name: San Juan 28-7 #44

Federal/ Indian Lease No: E-290-28

CA No.: _____

Unit : A

Legal Description: 27N-7W-2 660' FNL & 765' FEL

County: Rio Arriba

Load line valves :
Sealed during Production

Drain line valves :
Sealed during Production

Production Line valve:
Sealed during sales

This lease is subject to the site security plan for
San Juan Basin Operations. The plan is located at:
Conoco Inc.
3315 Bloomfield Hwy
Farmington, NM