

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 copy to
appropriate
District Office
and 1 copy to
the Santa Fe Office

(Revised 3/9/94)

PIT REMEDIATION AND CLOSURE REPORT

Operator: _____ Conoco, Inc. _____ Telephone: _____

Address: _____ 3315 Bloomfield Hwy. _____

Facility Or: _____ San Juan 28-7 #44 _____
Well Name

Location: Unit or Qtr/Qtr Sec _____ A _____ Sec _____ 2 _____ T _____ 7N _____ R _____ 7W _____ County _____ Rio Arriba _____

Pit Type: Separator ☒ Dehydrator _____ Other _____

Land Type: BLM _____, State ☒ Fee _____ Other _____

Pit Location: Pit dimensions: length _____ 6' _____, width _____ 6' _____, depth _____ 2' _____

(Attach diagram)

Reference: wellhead ☒ other _____

Footage from reference: _____ 93' _____

Direction from reference: _____ 130 _____ Degrees ☒ East North ☒
of
_____ West South _____

Depth To Ground Water
(Vertical distance from
contaminants to seasonal
high water elevation of
ground water.)

Less than 50 feet (20 points)
50 feet to 99 feet (10 points)
Greater than 100 feet (0 points) 20

Wellhead Protection Area:
(Less than 200 feet from a private
domestic water source, or; less than
1000 feet from all other water sources.)

Yes (20 points)
No (0 points) 0

Distance To Surface Water:
(Horizontal distance to perennial
lakes, ponds, rivers, streams, creeks,
irrigation canals and ditches.)

Less than 200 feet (20 points)
200 feet to 1000 feet (10 points)
Greater than 1000 feet (0 points) 0

RANKING SCORE (TOTAL POINTS): 20

Date Remediation Started: _____ Date completed: _____

Remediation Method: Excavation _____ Approx. cubic yards _____
(Check all appropriate
sections.) Landfarmed _____ Insitu Bioremediation _____

Other _____

Remediation Location: Onsite _____ Offsite _____
(i.e. landfarmed onsite,
name and location of
offsite facility) _____

General Description of Remedial Action: _____ No Remediation Necessary _____

Ground Water Encountered: No ☒ Yes _____ Depth _____

Final Pit:
Closure Sampling:
(if multiple samples,
attach sample results
and diagram of sample
locations and depths)

Sample location _____ 3' below pit bottom _____

Sample depth _____ 5' _____

Sample Date _____ 11/13/2000 _____ Sample time _____ 10:25 AM _____

Sample Results

Benzene(ppm) _____ .0039

Total BTEX(ppm) _____ .0157 _____

Field headspace(ppm) _____ 10.0 _____

TPH _____ 0.9 _____


Ground Water Sample: Yes _____ No ☒ (If yes, attach sample results)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Date

9/16/01

Signature



Printed Name
and Title

John Cofer, Environmental Director

ENVIROTECH LABS

PRACTICAL SOLUTIONS FOR A BETTER TOMORROW

EPA METHOD 8021 AROMATIC VOLATILE ORGANICS

Client:	Conoco Inc	Project #:	707003-263
Sample ID:	BDP	Date Reported:	11-14-00
Laboratory Number:	18558	Date Sampled:	11-13-00
Chain of Custody:	8305	Date Received:	11-13-00
Sample Matrix:	Soil	Date Analyzed:	11-14-00
Preservative:	Cool	Date Extracted:	11-13-00
Condition:	Cool & Intact	Analysis Requested:	BTEX

Parameter	Concentration (ug/Kg)	Det. Limit (ug/Kg)
Benzene	3.9	1.8
Toluene	7.7	1.7
Ethylbenzene	ND	1.5
p,m-Xylene	ND	2.2
o-Xylene	4.1	1.0
Total BTEX	15.7	


ND - Parameter not detected at the stated detection limit.

Surrogate Recoveries:	Parameter	Percent Recovery
	Trifluorotoluene	100 %
	Bromofluorobenzene	100 %

References: Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA, December 1996.

Method 8021B, Aromatic Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846, USEPA, December 1996.

Comments: San Juan 28-7 #44. OVM 10


Analyst


Review

ENVIROTECH LABS

PRACTICAL SOLUTIONS FOR A BETTER TOMORROW

EPA METHOD 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons


Client:	Conoco Inc.	Project #:	707003-263
Sample ID:	BDP	Date Reported:	11-14-00
Laboratory Number:	18558	Date Sampled:	11-13-00
Chain of Custody No:	8305	Date Received:	11-13-00
Sample Matrix:	Soil	Date Extracted:	11-13-00
Preservative:	Cool	Date Analyzed:	11-14-00
Condition:	Cool and Intact	Analysis Requested:	8015 TPH


Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5 - C10)	ND	0.2
Diesel Range (C10 - C28)	0.9	0.1
Total Petroleum Hydrocarbons	0.9	0.1

ND - Parameter not detected at the stated detection limit.

References: Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846, USEPA, December 1996.

Comments: **San Juan 28-7 #44. OVM 10**


Analyst


Review

08305

ENVIROTECH INC.

50380


ENVIROTECH INC.

**5796 U.S. Highway 64
Farmington, New Mexico 87401
(505) 632-0615**

Lease Name: San Juan 28-7 #44 MV

Operator: Bob Williams

Date: 2/01 2000



Lease Name: San Juan 28-7 #44

Federal/ Indian Lease No: E-290-28

CA No.: _____

Unit : A

Legal Description: 27N-7W-2 660' FNL & 765' FEL

County: Rio Arriba

Load line valves :
Sealed during Production

Drain line valves :
Sealed during Production

Production Line valve:
Sealed during sales

This lease is subject to the site security plan for
San Juan Basin Operations. The plan is located at:
Conoco Inc.
3315 Bloomfield Hwy
Farmington, NM