Form 3-331 (May 1963)	UNITED STATES DEPARTMENT OF THE INTERI	SUBMIT IN TRIPLICATE Budget Bureau No. 42-R1424.  (Other instructions on reverse side)  5. LEASE DESIGNATION AND SERIAL NO.
	GEOLOGICAL SURVEY	SF 079367 /
SU (Do not use th	ON WELLS  ack to a different reservoir.  oposais.)	
OIL GAS WELL WELL	7. UNIT AGREEMENT NAME San Juan 27-5 Unit 8. FARM OR LEASE NAME	
2. NAME OF OPERATOR El Paso Na	San Juan 27-5 Unit	
PO Box 990	160	
4. LOCATION OF WELL See also space 17 h At surface	(Report location clearly and in accordance with any elow.) 1800'N, 1500'W	So. Blanco Pictured Cliff.  11. BEC., T., R., M., OR BLK. AND BURVEY OR AREA
14. PERMIT NO.	15. ELEVATIONS (Show whether DF	Sec. 31, T-27-N, R-5- NMPM 12. COUNTY OR PARISH 13. STATE
14. FEB.RII NO.		6577'GL Rio Arriba NM
TEST WATER SHU	1	SUBSEQUENT REPORT OF:  WATER SHUT-OFF  FRACTURE TREATMENT  ALTERING CASING
TEST WATER SHU' FRACTURE TREAT SHOOT OR ACIDIZE	PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON*	WATER SHOT OF STATE O
REPAIR WELL (Other)	CHANGE PLANS	(Other)  (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
17. DESCRIBE PROPOSED proposed work. nent to this work	If Well is directionally drined, give bubble total	t details, and give pertinent dates, including estimated date of starting any tions and measured and true vertical depths for all markers and zones perti-
9-15-73	surface casing, 128' set at 140'	hole. Ran 4 joints 8 5/8", 24#, K-55 . Cemented with 118 cu.ft. cement.
	Circulated to surface. WOC 12	hours, held 600#/30 minutes.
		SEP 20 1033

18. I hereby certify that the foregoing, is true and correct	Drilling Clerk	September 17, 1973
(This space for Federal or State office use)		DATE
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE	8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8

\*See Instructions on Reverse Side