

DEPARTMENT OF THE INTERIOR (SEE INSTRUCTIONS ON REVERSE SIDE)
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. SF-080213	
2. NAME OF OPERATOR Union Oil Company of California (dba Unocal)		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P.O. Box 850, Bloomfield, New Mexico 87413		7. UNIT AGREEMENT NAME Rincon Unit	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1651' FSL, 1500' FWL		8. FARM OR LEASE NAME	
14. PERMIT NO.		9. WELL NO. #200	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6750' GR		10. FIELD AND POOL, OR WILDCAT Otero Chacra	
		11. SEC., T., R., M., OR BLK. AND SURVEY OF AREA K Sec. 33, T27N, R7W	
		12. COUNTY OR PARISH Rio Arriba	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) Request for S.I. status <input checked="" type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
(Other) <input type="checkbox"/>	

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

The Rincon Unit #200, was granted a temporary one-year shut-in status by the BLM on August 23, 1988. The current gas price has not improved over the past year, hence a workover at this time would not be economically feasible. Given our current high level of activity in the area and other time constraints, Union Oil Company of California (dba Unocal) requests an additional six (6) month temporary shut-in status for this well in order to allow time to fully evaluate its remaining potential.

RECEIVED
SEP 22 1989

THIS APPROVAL EXPIRES FEB 23 1990 OIL CON. DIV. DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED Bill Hering

TITLE Area Petroleum Engineer

DATE August 25 1989

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

WH/s1

*See Instructions on Reverse Side

APPROVED	
SEP 19 1989	DATE
Ken Townsend AREA MANAGER FARMINGTON RESOURCE AREA	