

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)


1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name San Juan 27-5 Unit
2. Name of Operator El Paso Natural Gas Company	8. Farm or Lease Name San Juan 27-5 Unit
3. Address of Operator Box 990, Farmington, New Mexico 87401	9. Well No. 181
4. Location of Well UNIT LETTER <u>E</u> <u>1730</u> FEET FROM THE <u>North</u> LINE AND <u>1010</u> FEET FROM THE <u>West</u> LINE, SECTION <u>23</u> TOWNSHIP <u>27-N</u> RANGE <u>5-W</u> NMPM.	10. Field and Pool, or Wildcat Tapacito Pictured Cliff
15. Elevation (Show whether DF, RT, GR, etc.) 6543' GL	12. County Rio Arriba

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-26-74 Spudded well. Drilled surface hole.

3-27-74 Ran 3 joints 8 5/8", 24#, J-55 surface casing, 115' set at 115' GL. Cemented with 106 cu. ft. cement. Circulated to surface. Waited on cement 12 hours.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED D. G. Luccas TITLE Drilling Clerk DATE 4-1-74

APPROVED BY [Signature] TITLE [Signature] DATE 4-15-74

CONDITIONS OF APPROVAL, IF ANY: