Torm 3160-5 November 1983) Formerly 9-331) UNITED STATES SUBMIT IN TRIPLICATE (Other Instructions on re- BUREAU OF LAND MANAGEMENT	Budget Bureau No. 1004-0135 Expires August 31, 1985 5. LEASE DESIGNATION AND SERIAL NO. SF 079402-B
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
OIL GAB OTHER 2. NAME OF OPERATOR	7. UNIT AGREEMENT NAME San Juan 2755 Unit 8. FARM OR LEASE NAME
F1 Paso Natural Gas Company 3. ADDRESS OF OFERATOR PO Box 4289 Farmington NM 87499 4. Locarion of Well (Report location clearly and in accordance with any State requirements.*	San Juan 27-5 Unit 9. Wall No. 182
Location of well (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1600'N, 1500'E	Tapacito Pic.Cliffs 11. SEC., T., B., M., OR BLE. AND SURVEY OF AREA
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, BT, CR, etc.)	Sec. 23, T-27-N, R-5-W NMPM 12. COUNTY OR PARISH 13. STATE
6551 GL PANISOTO PROCESSOR REAL RIO Arriba NM 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data	
FRACTURE TREAT BHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other)	EEPAIRING WELL ALTERING CASING ABANDONMENT*
It is intended to permanently repair a casing lead tubing and packer, setting a sand plug across the isolating the leak, and squeeze cementing the leak Following clean out, the casing will be tested to and packer rerun and the annulus filled with correspondents.	to by pulling the perforations, as necessary. 700 psi, the tubing
	CEIVE 1)
OIL	CON. DIV.
18. Phereby certify that the foregoing is true and correct SIGNED LOGA Shalleeld TITLE Drilling Clerk	PRRQVED
(This space for Federal or State office use) APPROVED BY	DATE // 1984 M. MILLENBACH

*See Instructions on Reverse Side

GAREA MANAGER