

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other ☐  
well well

2. NAME OF OPERATOR  
El Paso Natural Gas Company

3. ADDRESS OF OPERATOR  
P.O. Box 289, Farmington, NM 87401

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 1600'S, 1650'E  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐

(other) Isolate Casing Leak

☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐

5. LEASE

SF 079527

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

S. J. 27-4 Unit

8. FARM OR LEASE NAME

S. J. 27-4 Unit

9. WELL NO.

83

10. FIELD OR WILDCAT NAME

Tapacito Pictured Cliffs

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 26, T27N, R4W

12. COUNTY OR PARISH

Rio Arriba

13. STATE

New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

7304' G.L.

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*


On December 8, 1981 a packer was set on 1 1/4" tubing at 4118' to isolate the casing leak from the producing formation. If subject well's producing rate returns to the pre-casing leak rate, then the well will be repaired permanently. If the production rate does not return, then the well will be recommended for abandonment.

RECEIVED

DEC 18 1981

U. S. GEOLOGICAL SURVEY  
DURANGO, COLO.

Set @



Subsurface Safety Valve: Manu. and Type

18. I hereby certify that the foregoing is true and correct.

SIGNED

*William F. Clark*

TITLE

Production  
Engineer

DATE

December 14, 1981

ACCEPTED FOR RECORD

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY

TITLE

DATE

FARMINGTON DISTRICT

PV

NMOCC