UNITED STATES DADTMENT OF THE INTERIOR

	EASE	
SF	08067	4 3

UNITED STATES DEPARTMENT OF THE INTERIOR	5. LEASE SF 080674
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME San Juan 27-4 Unit 8. FARM OR LEASE NAME
1. oil gas well other 2. NAME OF OPERATOR	San Juan 27-4 Unit 9. WELL NO. 99
El Paso Natural Gas Company	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR Box 990, Farmington, New Mexico 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 815'S, 830'W	Basin Dakota 11. SEC., T., R., M., OR BLK, AND SURVEY OR AREA Sec. 16, T-27-N, R-4-W N. M. P. M.
AT SURFACE: 815-3, 650 W AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	12. COUNTY OR PARISH 13, STATE N. M.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	7274 GL
TEST WATER SHUT-OFF	
REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other)	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertined	e all pertinent details, and give pertinent dates, irectionally drilled, give subsurface locations and at to this work.)*
7-28-78 Spudded well. Drilled surface hole. Ra casing, 227' set at 241'. Cemented with surface. WOC 12 hours; held 600#/30 m	224 cu. ft. cement. Circulated to

Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct TITLE Drilling Clerk DATE

(This space for Federal or State office use)

DATE APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

AUG 7 1978

Facilities .