

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. NM 03547
2. NAME OF OPERATOR Caulkins Oil Company		6. IF INDIAN, ALLOTTER OR TRIBE NAME
3. ADDRESS OF OPERATOR Post Office Box 780, Farmington, New Mexico		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 940' from North and 1850' from West of 35 27N 6W		8. FARM OR LEASE NAME Breach F
14. PERMIT NO.		9. WELL NO. 10
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6596 DF		10. FIELD AND POOL, OR WILDCAT South Blanco
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 35 27N 6W
		12. COUNTY OR PARISH Rio Arriba
		13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)


17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD 3300'. Ran 3 1/2" EUE Tubing for Production String as follows:

0 to 3300' 106 joints. 3 1/2" EUE 8rd 9.30# J-55 Smls.

Cemented with 200 sacks Lodense cement followed with 50 sacks neat. Plug down 3:30 PM Sept. 19, 1974

Temperature survey run Sept. 20, 1974 showed top of cement at 2250'.



18. I hereby certify that the foregoing is true and correct

SIGNED

Charles Deque

TITLE

Superintendent

DATE

9-22-74

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side